

---

---

**APPENDIX K-3**

**WHEELER ARMY AIRFIELD INSTALLATION  
ACTION PLAN SITE LISTING**





## Wheeler Army Airfield Installation Action Plan Site Listing

IAP Number	Site Name	Description	COCs	Phases Complete	Future Response
LF01	Landfill 1	Landfill/Dump Site	VOCs halogenated organic compounds petroleum hydrocarbons oil and grease	PA/SI RI Risk Assessment	NFRAP DOH signed
DP02	Gulch Runway Dump	Landfill/Dump Site	VOCs halogenated organic compounds petroleum hydrocarbons oil and grease organochlorine pesticides metals PCBs	PA/SI RI Risk Assessment EE/CA Non-time Critical Removal Action	NFRAP DOH signed.
DP03	Kunia Gate Dump	Landfill/Dump Site	VOCs halogenated organic compounds petroleum hydrocarbons oil and grease herbicides chlorinated pesticides metals PCBs	PA/SI RI Risk Assessment EE/CA Non-time Critical Removal Action	NFRAP DOH signed  <i>Recommend periodic monitoring of landfill cover to ensure integrity.</i>
FT04	Fire Training Area	Fire Training Area	VOCs halogenated organic compounds PAHs petroleum hydrocarbons oil and grease metals PCBs	PA/SI RI Human Health Risk Assessment Ecological Risk Assessment	NFRAP DOH signed



## Wheeler Army Airfield Installation Action Plan Site Listing

IAP Number	Site Name	Description	COCs	Phases Complete	Future Response
SD05	Aircraft Parking / Wash Rack Area	Maintenance Areas/ Wash Areas	VOCs petroleum hydrocarbons oil and grease	PA/SI RI Risk Determination	NFRAP DOH signed
SD06	Aircraft Parking Area	Maintenance Areas/ Wash Areas	VOCs SVOCs petroleum hydrocarbons oil and grease	PA/SI RI Risk Determination	NFRAP DOH signed
WP07	Sanitary Sewer System along Santos Dumont Avenue	Sewer System	VOCs petroleum hydrocarbons oil and grease	PA/SI RI Risk Determination	NFRAP DOH signed
WP08	Abandoned Oxidation Ponds	Oxidation Pond	None identified	PA/SI	NFRAP DOH signed
AOC EA01	Former Aircraft Revetment	Maintenance Areas/ Wash Areas	VOCs SVOCs PAHs petroleum hydrocarbons metals	PA/SI	NFRAP
AOC EA02	Vehicle Wash Rack	Maintenance Areas/ Wash Areas	VOCs SVOCs petroleum hydrocarbons metals	PA/SI	NFRAP
AOC EA03	Hydraulic Lift Sump	Maintenance Areas/ Wash Areas	VOCs SVOCs petroleum hydrocarbons PCBs metals	PA/SI	No evidence of release into environment. Not eligible for IRP..
AOC EA04	Two Underground Storage Tanks	UST	VOCs PAHs petroleum hydrocarbons metals	PA/SI RA	NFRAP (See Tank Sites 235-1 and 235-2)



## Wheeler Army Airfield Installation Action Plan Site Listing

IAP Number	Site Name	Description	COCs	Phases Complete	Future Response
AOC EA05	Adjacent to POL Transfer Station	POL Storage Area	VOCs SVOCs petroleum hydrocarbons oil and grease metals	PA/SI	NFRAP
AOC EA06	Drum Disposal Area	Landfill/Dump Site	VOCs SVOCs PAHs PCBs metals	PA/SI	NFRAP concentrations of the COCs were below action levels.
AOC EA07	Active Aboveground Tank	AST	VOCs PAHs petroleum hydrocarbons	PA/SI	AST has been replaced and site is no longer a concern.
Site 10	Gulch Runway Landfill Number 3	Landfill/Dump Site	VOCs SVOCs PAHs petroleum hydrocarbons metals	PA/SI	NFRAP. No further remedial action recommended under IRP.



# Wheeler Army Airfield Installation Action Plan Site Listing

IAP Number	Site Name	Description	COCs	Phases Complete	Future Response
Site 11	Aircraft Revetments	Maintenance Areas/ Wash Areas	VOCs SVOCs PAHs metals	PA/SI	NFRAP
Site 12	Fire Protection Training Area 2	Fire Training Area	VOCs SVOCs PAHs metals	PA/SI	NFRAP
Site 13	Hot Mix Plant	Hot Mix Plant	VOCs SVOCs PAHs metals	PA/SI	NFRAP
Site 14	Earthen Sump at Former Gas Station	Maintenance Areas/ Wash Areas	VOCs SVOCs PAHs petroleum hydrocarbons metals	PA/SI	RI/FS



## Wheeler Army Airfield Installation Action Plan Site Listing

IAP Number	Site Name	Description	COCs	Phases Complete	Future Response
Site 15	ASTs 1001 & 1002	AST	VOCs SVOCs petroleum hydrocarbons metals	PA/SI	NFRAP
Site 16	Small Arms Firing Range	Firing Range	metals	PA/SI	Range is inactive but not closed. SI warranted upon closure of range.
Site 17	Wheeler Network Segment Control Center	Antenna Site	VOCs SVOCs petroleum hydrocarbons PAHs polychlorinated biphenyls metals	PA/SI	RI/FS. The investigation should focus on delineating the nature and extent of contamination along the western boundary of the site where patches of waste tar were observed.
Site 18	Unauthorized Dump Area	Dump Site	None identified	PA/SI	NFRAP
UST 1112-1	UST Site 1112-1	UST	VOCs petroleum hydrocarbons lead	PA/SI Remedial Action	NFRAP
UST 111-1	Former Waste Oil UST 111-1	UST	VOCs PAHs petroleum hydrocarbons metals	PA/SI Remedial Action	NFRAP



# Wheeler Army Airfield Installation Action Plan Site Listing

IAP Number	Site Name	Description	COCs	Phases Complete	Future Response
UST 107-1	UST Site 107-1	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 114-1	UST Site 114-1	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 800-X	UST Site 800-X	UST	VOCs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 800-3	UST Site 800-3	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 105-1	UST Site 105-1	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 235-1&2	UST Site 235-1 and 235-2	UST	VOCs PAHs petroleum hydrocarbons metals	PA/SI Remedial Action	NFRAP
UST 208-1	UST Site 208-1	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 208-2	UST Site 208-2	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 108-1&X	UST Site 108-1 and 108-X	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP
UST 1004-1,2,3&4	UST Site 1004-1, 1004-2, 1004-3, and 1004-4	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP



## Wheeler Army Airfield Installation Action Plan Site Listing

IAP Number	Site Name	Description	COCs	Phases Complete	Future Response
UST D1	UST Site D1	UST	VOCs PAHs petroleum hydrocarbons	PA/SI Remedial Action	NFRAP

*This page intentionally left blank.*